

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	o completed to the state of		5000			
prior to port	oe completed in its entirety	y to constitute a v	alid maintenance p	permit. This permit n	nust be completed	
	forming maintenance activi	ties and remain o	n-site for the dura	tion of the maintenar	ice activity.	
Date of Maintenance	e: Reason	for Maintenance:	Ruhry			
Property Address: $\underline{1}$	0606 Marel	ALL.	Property Owner's N	lame: Truy Co	shett	
Municipality:	1.		entification Number			
Maintenance Permit	No: <u>C6109w12560</u>				_	
		Maintainer Haine a	ild License No. Pink	ky's Environmental Sev	ver Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
✓ Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (i	f no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintena	Ince Hole When (
			enter authorization co	ode)		
	ecurely replaced? Yes					
evidence of dam	of tank leakage from a sep	otic, holding, preti	eatment or pump	tank below the opera	iting depth or	
evidence of dan	naged, cracked, or structur	ally unsound main	tenance hole cove	rs? L Yes No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 15cc	gal Tank #2	gal Pretreatment	tank øa	al Pump Tank	gal	
. Other information	: List any troubleshooting,	minor repairs cor	ducted tank safe	ty concerns or other	gat	
	3,		idacted, turn sare	ty concerns, or other	concerns.	
			The state of the s			
. Location of septage	e disposal: St gan	1				
	7					
	Pinkv'	s <mark>Environmental</mark> Se	wer Service Inc			
		PO Box 35				
		After AM EE				

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.