

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit r	nust be completed	
	orming maintenance activi					
Date of Maintenance:	1-3-19 Reason	for Maintenance:	Routing	2		
	1977 Arcola				elshons	
	Mucita zip: 550					
	10:18054513715				wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
$\square$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintena	ance Hole Other (e	enter authorization co	ode)		
2. Were all covers se	ecurely replaced? Yes	□No in f	lower Gans	0 -		
	of tank leakage from a se				ating depth or	
	aged, cracked, or structur				ating depth of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ► No	☐ Yes ►No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 (000	gal Tank #2	_gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or othe		
6. Location of septage	e disposal: ) 1. pao	1		NE PRODUCT		
	•	•				
	Pinky	's Environmental Se	ewer Service Inc.			
		20.5				

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.