DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 3-28-16 Reason for Maintenance: 5chelaled plaigtenance							
Property Address: 7550 Lqverne Ave S Property Owner's Name: Pavide Holly Finkus Municipality: Cottage Grove State Zip Code 55016 GEO Code/Property I.D. #: Tank Measurements (must be completed if tanks NOT pumped)							
Municipality: Cottage Grove State Zip Code 55016 GEO Code/Property I.D. #:							
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)					
Tank(s) Pumped		Liquid Level of Tank in. Sludge Level in. Scum Level in.					
Sludge and scum measured.		Elquid Level of Turns		_		*	
Do tanks need to be pumped?		Total (Sludge + Scum) / Liquid Level = % Sludge & Scum					
Yes No (If no provide measurements)					* Tank must be pumped if this value		
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be purified it this value is greater than 25%.							
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain							
Explanation:					Laterana hala h		
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:							
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance							
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.							
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit							
Tank#1 Yes No Verificatio Method Used:							
Tank#2 Yes No Verificatio Method Used:							
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?							
		Leaking Out	Leaking In		Cover Damage		
	Tank	T Yes No	☐ Yes ☐		☐ Yes ☐ No		
	Septic/Holding Tank #1	□ Yes □ No	☐ Yes ☐		☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐		☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐		☐ Yes ☐ No		
Pump rank 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
6. How many gallons of septage were removed?							
Tank #1 1250 Tank #2 Pretreatment Tank Pump Tank							
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.							
8. Certification:	I hereby certify as a State of Mi and made the observations, or	directly supervised of	iers in the pen	Office of the	13)00.		
W6621 610th Ave. Ellsworth, WI 54011							
Maintainer's Name: Ron's Sewer Service Maintainer's Address: Maintainer's License #: 2103 Maintainer's Phone #: 715-749-0153 Maintainer's Signature Maintainer's Address: Odd: 62280m 0084							
Maintainer's Signature Washing Manual Date: 3-28-16							