DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 10/1/15—Reason for Maintenance:					
Property Address: 20340 Kee As Ave N Property Owner's Name: Mike Moszer					
Municipality:	vest Lake	State Zip Code _	GEO	Code/Property I.D. #:	
What w	as done to the system?	Tank Measu	rements (must be o	completed if tanks NOT pur	mped)
Sank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Yes No (If no provide measurements)		Liquid Level of Tank Total (Sludge + Scum	in. Sludg		*
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes \[\text{No please explain} \]					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Tyes No Verificatio Method Used: Usual/fleces					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
automagnar, area	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_
	Pretreatment Tank	☐ Yes ☐ No	Yes No	Yes No	
	Pump Tank	☐ Yes ☐ No	Yes No	Yes No	<u>.</u>
6. How many gallons of septage were removed?					
Tank#1	ンム Tank #2	Pretreatment Tank	.	Pump Tank	_
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	•				
8. Certification:	I hereby certify as a State of M and made the observations, o				
Maintainer's Name: A & B Sanitation Service Maintainer's Address: P.O. Box 247 -Scandia					
Maintainer's License #: 3885 Maintainer's Phone #: 651-433-2000					
Maintainer's Signature Date:					