DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance /////, Reason for Maintenance: Becks				
Property Address: 8032 Hiller De, Trd Property Owner's Name: Johns Hon Early				
•	tate Jip Code	GEO Code/l	Property I.D. #:	
What was done to the system?	Tank Measur	ements (must be comple	eted if tanks NOT pun	nped)
Tank(s) Pumped	Liquid Level of Tank	in. Sludge Leve	ı in. Scum Lev	el in.
Sludge and scum measured.	-			
Do tanks need to be pumped?	Total (Sludge + Scum)	/ Liquid Level	= % Sludge &	Scum *
Yes No (If no provide measurements)]	·	Tank must be pumpe	d if this value
1. Access used to remove septage: (Smaintenance Hole Other (Go to #3 below) is greater than 25%.				
2. If maintenance hole was used, were all covers securely replaced? No please explain				
Explanation:				
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:				
l. (own	er's name), refuse to allo	w the removal of solids a	nd liauids through the	maintenance
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
Tank#1 Yes No Verificatio Method Used: Usual Block				
Tank#2 Yes No Verificatio Method Used: // Plas de				
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
· Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	T Yes T No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
6. How many gallons of septage were removed?				
The state of the s				
Tank#1 / 200 Tank#2 / 200	Pretreatment Tank			-
7. Other information: List any troubleshooting	minor repairs conduct	ed, tank safety concern	s, or other concerns.	
· · · · · · · · · · · · · · · · · · ·				
8. Certification: I hereby certify as a State of Min and made the observations, or o				pd #25
Maintainer's Name: A & B Sanitation Service Maintainer's Address: P.O. Box 247 - Scandia				
Maintainer's License #: 3885 Maintain	er's Phone #: 651-433-2	000		
Maintainer's Signature Date:				
· • · · · ·				