

GÖVERNMENT CENTER 14949 62nd STREET NORTH P. O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| | - Constitution of the Cons | | | son's Sewer Service/L2 | Carrier Control |
|--|--|---|------------------------------------|---|-----------------|
| ☐ Tank(s) Rumped☐ Sludge and scum Do tanks need to | méasured Dé pumped? fino provide measurement | Liguid Level of Studge Level in Studge + Scum | Tank in / Liquid | Scum Level in Tank, Level X 100 anks must be pumped | , in |
| Were all covers s Is there evidence | emove septage: Maintel ecurely replaced? Yes of tank leakage from a se | i □No Eptic, holding, pret | reatment or nume | tank below the enough | ating depth or |
| evidence of dan | naged, cracked, or structu | rally unsound mair | ntenance hole cove | ers? Yes No | • |
| evidence of dan | Tank | rally unsound mair Leaking Out | Leaking In | Cover Damage | st. |
| evidence of dan | rageu, Cracked, or structt | rally unsound mair | ntenance hole cov | ers? Yes No | á. |
| evidence of dan | Tank | rally unsound mair Leaking Out | Leaking In | Cover Damage | .đ. |
| evidence of dan | Tank Septic/Holding Tank #1 | Leaking Out Ves No | Leaking In Yes MNo | Cover Damage Yes No Yes No | <i>3</i> |
| evidence of dan | Tank Septic/Holding Tank #1 Septic/Holding Tank #2 | Leaking Out Yes No | teaking in ☐ Yes ☑ No ☐ Yes ☐ No | Cover Damage Yes No Yes No Yes No | .d. |

Olson's Sewer Service Inc. 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082