

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance | Plulaon Reason | for Maintenance: | | | | |
|--|--------------------------|---|--|--------------|-------------|--|
| Property Address: 10830. 2282 St. No- Property Owner's Name: M. Math | | | | | | |
| Municipality: Se 🛰 | lia ZIP:55 | 73 Property Ide | entification Numbe | r: | | |
| Maintenance Permit I | 7008 2903 a 8065 | | | | | |
| | <u> </u> | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | | |
| ☐ Sludge and scum measured Do tanks need to be pumped? | | Liquid Level of Tank in | | | | |
| | | | Sludge Level in Tank in Scum Level in Tank in | | | |
| | | Sludge + Scum / Liquid Level X 100 = % Sludge & Scum | | | | |
| \square Yes \square No (if no provide measurements) | | - % studge & sc | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to rea | nove septage: Maintena | nce Hole 🗌 Other (| enter authorization c | ode) | | |
| 2. Were all covers securely replaced? Yes No | | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | | |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | 1 | |
| | Septic/Holding Tank #1 | ☐ Yes ☐No | ☐ Yes 🛛 No | ☐ Yes ⊠No | | |
| | Septic/Holding Tank #2 | ☐ Yes ₺ No | ☐ Yes 🎾 No | ☐ Yes No | , | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes 🗖 No | ☐ Yes 🕅 No | ☐ Yes \No | | |
| 4. How many gallons | of septage were removed? | • | | , | | |
| Tank #1 500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal | | | | | | |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | | |
| | | ** | 20 | | | |
| 4 Location of control | 2 4 Museub | 181 | | | | |
| 6. Location of septage disposal: | | | | | | |