DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11/04/15 Reason	n for Maintenance: \mathcal{P}_{c}	OUTINE MAINT			
Property Address: 16190 220th Str	ect Prope	rty Owner's Name: TEP	FREY & DIANNA P	HILL	
Municipality: SCANDIA	State M// Zip Code	55073 GEO Cod	e/Property I.D. #:		
What was done to the system?	Tank Mea	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Lovel of Tap	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Sludge and scum measured.	Liquid Level of Tan	III. Sludge Level Scull Level			
Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measureme	Total (Sludge + Scu	um) / Liquid Leve	el = % Sludge & Scum	* 	
1. Access used to remove septage: KMaint	enance Hole Other (Go to #3 below)	 Tank must be pumped if the is greater than 25%. 	nis value	
2. If maintenance hole was used, were all cover	ers securely replaced?	Yes No please expla	in		
Explanation:					
3. If owner refuses to allow a Subsurface Se them complete and sign the following sta		n (SSTS) to be pumped th	rough the maintenance hole	, have	
l,	owner's name), refuse to	allow the removal of solid:	s and liquids through the main	tenance	
hole. I understand that removal of solids ar	nd liquids through other a	ccess points is not conside	red maintenance.		
4. Is the tank designed as a leaky tank? <i>examp</i>	le: seepage pit, cesspool, d	rywell, leaching pit	9		
Tank#1 Yes No Verificatio Metho	od Used: VISU	AL			
Tank#2 Yes No Verificatio Metho	od Used:	*	e		
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou			w the operating depth or evi	idence of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	T Yes X No	Yes A No	Yes Fi No		
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
Pretreatment Tank	/ Yes / No	☐ Yes ☐ No	T Yes T No		
Pump Tank	☐ Yes ☐ No	Yes No	Yes No		
6. How many gallons of septage were remo	ved?				
Tank #1 1250 Tank #2	Pretreatment Ta	nkPu	mp Tank		
7. Other information: List any troubleshoo	ting, minor repairs cond	ucted, tank safety conce	rns, or other concerns.		
8. Certification: I hereby certify as a State of and made the observations	, or directly supervised ot	ners in the performance of	this job.		
Maintainer's Name: Ross' Sewer Service	Maintain	er's Address: 9288 County	Rd 5 NE North Branch, MN 550	56	
Maintainer's License #: L3448 Main	tainer's Phone #: 651-67	4-4349	š		
Maintainer's Signature	L-	Date: //	-4-15		