

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

1	e: 6/21/2019 Reason	n for Maintenance:	Scheduled			
Property Address: _	14502 Manning T	Fl. N.	Property Owner's i	vame: Alan to Dea	Deb Feyer	
Municipality: _ <u>_</u>						
Maintenance Permit	No: 1877 15519	Maintainer Name a	and License No. Ols	on's Sewer Service/L2	16	
			- average and a second			
हैं!नावद्य	ekreteta Mandelantare		A CONTRACT	tantanase f same i	(CF ovinteral)	
Tank(s) Pumped Studge and soum measured			Studge Level of Tank in Scum Level in Tank in Studge • Scum / Liquid Level X 100			
Do tanks need t		I - 9 Studio & Co		nks must be pumped in		
ES TES LI NO (if no provide measurements)]				
1. Access used to r	emove septage: El Mainten	ance Hole Other (enter authorization c	ođe)		
2. Were all covers	securely replaced? 🖾 Yes	□ No	· •		4	
3. Is there evidence	e of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the opera	ating depth or	
evidence of da	maged, cracked, or structu	rally unsound main	itenance hole cove	rs? 🗆 Yes 🖾 No		
	Tank	Leaking Out	Leaking In	Cover Damage	<i>:</i>	
	Septic/Holding Tank #1	☐ Yes ❷No	☐ Yes ♣ No	☐ Yes 台No		
	1					
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes 🖾 No	☐ Yes Æ No		
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ੴNo☐ Yes ☐ No	☐ Yes ☐No		
			(W)			
Tank #1 1000	Pretreatment Tank Pump Tank as of septage were removed gal Tank #2	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☒ No t tank ga	☐ Yes ☐ No ☐ Yes-ि No ☐ Yes-ि No		
Tank #1 1000	Pretreatment Tank Pump Tank as of septage were removed	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☒ No t tank ga	☐ Yes ☐ No ☐ Yes-ि No ☐ Yes-ि No		
Tank #1 1000	Pretreatment Tank Pump Tank ns of septage were removed gal Tank #2 1000 on: List any troubleshooting	Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☒ No t tank ga	☐ Yes ☐ No ☐ Yes-ि No ☐ Yes-ि No		

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082