

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location 2015					
Address 1082	4 Hudson	Blucl		Telephone Number	
City Lake	Elmo	State _{MN} Z	(IP5504) Pr	operty ID No./GEO Code	
Owner Pet Images Country Inn Pumping Date 7/16/15					
		Contra	CALLED CONTRACTOR AND A CONTRACTOR OF THE CONTRACTOR AND ADDRESS O		
Maintainer MEY	ER SEWER	MPCA License N	10. 915	Telephone Number 651-	459-016
What was done to the system? Report Liquid Capacity in Gallons					
Tank(s) Pumped	1		Tank 1: 1500	Pumped Tank 2:	☐ Pumped
Sludge and scum			Tank 3:	Pumped Tank 4:	Pumped
Do tanks need to	•			- Tank in	
Yes No (If no provide measurements below) Total Gallons Pumped: 1500					
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.					
-					
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped					
Tank Length	in. X Tank Width	in. 🗶 Tank Dep	oth in. =	Tank Volume (cubic inches)	
Tank Radius	in. 🗶 Tank Radius	in. X 3.14 =	Tank Volume (cul	oic inches)	
Tank Volume (cu. in.)	/ 231.01 :	Liquid Capacity	Gallons /	Tank Depth in. = Gallons	/Inch
Sludge Level	in. X Gallons Per Inch	= Sludge Volu	ume Gallo	ns	
Scum Level	in. X Gallons Per Inch	= Scum Volur	me Gallo	ns	
Sludge Volume	+ Scum Volume	= Total Sludg	e and Scum Volume	g Gallons	
Total Sludge and Scum Volume / Liquid Capacity = Percent Sludge and Scum in Tank %					
				*Tanks must be pumped if ei following conditions exist: 1. The top of the sludge layer	•
Scum Layer		III III	-	12 inches from the bottom o	f the outlet
Effluent		from ir	Pepth measured overt of outlet b bottom of tank	baffle; or 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid	
Sludge Layer				capacity.	
Signature ///		Date	7/16/5	Reset For	m.