



Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 6-5-2019 Reason for Maintenance: ROUTINE
Property Address: 18850 FOREST ROMAN FOREST LAKE, MN 55025 Property Owner's Name: RICK REAULIEY
Municipality: FOREST LAKE ZIP: 55025 Property Identification Number:
Maintenance Permit No: e756dow15321 Maintainer Name and License No. ROSS' SEWER SERVICE L3448

Maintenance Performed: [X] Tank(s) Pumped, [ ] Sludge and scum measured. Tank Measurement (must be completed if tanks NOT pumped): Liquid Level of Tank, Sludge Level in Tank, Scum Level in Tank, Sludge + Scum / Liquid Level X 100 = % Sludge & Scum. Tanks must be pumped if 25% or greater.

- 1. Access used to remove septage: [X] Maintenance Hole [ ] Other (enter authorization code)
2. Were all covers securely replaced? [X] Yes [ ] No
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? NO

Table with 4 columns: Tank, Leaking Out, Leaking In, Cover Damage. Rows include Septic/Holding Tank #1, Septic/Holding Tank #2, Pretreatment Tank, and Pump Tank.

- 4. How many gallons of septage were removed? Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

6. Location of septage disposal: 29052 DIMABLO ST NE NORTH BRANCH, MN

RECEIVED JUN 21 2019

PUBLIC HEALTH