

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

System Location
Telephone Number
State MN ZIP 550/6 Property ID No./GEO Code
Pumping Date 9/2/1/5
Contractor
MPCA License No. 915 Telephone Number 651-459-016.
Report Liquid Capacity in Gallons
Tank 1: 15000 Pumped Tank 2: Pumped
Tank 3: Pumped Tank 4: Pumped
Total Gallons Pumped: 1500
system): NOTE: This does not serve as a compliance inspection.
nents-Use Only If Tank(s) Were NOT Pumped
in. X Tank Depth in. = Tank Volume (cubic inches)
in. X 3.14 = Tank Volume (cubic inches)
quid Capacity Gallons / Tank Depth in. = Gallons/Inch
= Sludge Volume Gallons
= Scum Volume Gallons
= Total Sludge and Scum Volume Gallons
uid Capacity = Percent Sludge and Scum in Tank // // // // // // // // // // // // //
*Tanks must be pumped if either of the
following conditions exist: 1. The top of the sludge layer is less than
12 inches from the bottom of the outlet
Tank Depth measured baffle; or 2. Total sludge and scum volume is greate
than 25 percent of the tank's liquid

pipe to bottom of tank capacity.

1