Fd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

14949 62nd STREET NORTH P 0780 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 1717: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenant	e: <u>(1) 25 P</u> Rea	son for Maintenance		ed	ance activity.
Property Address:		1 1 7		Name: Shaun	Coller
Municipality: <u></u>	anne ZIP: 5	564 Property I			
Maintenance Permi	t No: 435 015958			son's Sewer Service/L	216
Anne	ar-intel Mandontas	Teans de	enderster (masses	— сполька Тенк	Mile interest
Tank(s) Rumped Sludge and scun Do tanks need I Yes 🗆 No (measured	Sludge Gevel in Sludge • Scum	/ 1 liquid	Scum Level in Tank Level X 1,00 anks must be pumped	
 Were all covers Is there evidence 	emove septage: A Mainte securely replaced? A Ye e of tank leakage from a s maged, cracked, or structi	s 🗆 No eptic, holding, prei urally unsound mail	reatment or pump ntenance hole cov	tank holow the oner	ating depth or
2 EX	Tank	Leaking Out	Leakingin	Cover Damage	f
•	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Ves Æ No	☐ Yes ₽No	
3	Septic/Holding Tank #2	☐ Yes-☐No	☐ Yes ☐ No	☐ Yes-☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	- Car
-	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1600	s of septage were removed gal Tank #2 <u>1000</u> n: List any troubleshooting	_ gal Pretreatment	tank ga	al Pump Tank ty concerns, or other	gal concerns.
Location of septag	e disposal: Mitvo	Strail			

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082