

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

14949 62nd STREET NORTH P.O. BOX 6 STILL WATER, MN 55082-0006 Office: 651-430-6655 197Y: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on site for the duration of the maintenance activity.

operty Address	1532-15th St. B	t. No.	Property Owner's	Name: ToNatho	in Hack
unicipality: 3	Ne Elmo ZIP:		lentification Numb	-	, , , , ,
aintenance Perr				son's Sewer Service/L2	16
\ <u></u>	3344159.56				
otto.	tickeristet (f. 1721) elejetise 1843: Felet - 1721 elejetise	Total: Ass	en for designation (1911) o	a control of core	MO Municipal
		Sludge Level ir Sludge • Scum	/ Liguid	Scum Level in Tank Level X 100 anks must be pumped i	
•	remove septage: Mainte		(enter authorization o	code)	.•
Were all cover is there evider	s securely replaced? Ore nce of tank leakage from a s lamaged, cracked, or structi	s 🗆 No eptic, holding, pret urally unsound mail	reatment or pump ntenance hole cov	tank below the opera	iting depth o
Were all cover is there evider	s securely replaced? We note of tank leakage from a silamaged, cracked, or structions.	s 🗆 No eptic, holding, pret urally unsound mail Leaking Out	reatment or pump ntenance hole cove Leading In	tank below the opera ers?	iting depth o
Were all cover s there evider	s securely replaced? Ore nce of tank leakage from a s lamaged, cracked, or structu Tank Septic/Holding Tank #1	s 🗆 No eptic, holding, pret urally unsound mail	reatment or pump ntenance hole cov	tank below the opera ers?	iting depth o
Were all cover Is there evider	s securely replaced? We note of tank leakage from a silamaged, cracked, or structions.	s 🗆 No eptic, holding, pret urally unsound mail Leaking Out	reatment or pump ntenance hole cove Leading In	tank below the operators? Yes No Cover Damage Yes No	iting depth o
Were all cover Is there evider	s securely replaced? Ore nce of tank leakage from a s lamaged, cracked, or structu Tank Septic/Holding Tank #1	s 🗆 No eptic, holding, prei urally unsound mail Leaking Out ☐ Yes 🖾 No	reatment or pump ntenance hole cove Leaking in	tank below the operators? Yes No Cover Damage Yes No	iting depth o
Were all cover is there evider	rs securely replaced?	s No eptic, holding, prei urally unsound mail Leaking Out Ves No Ves No	reatment or pump ntenance hole cove Leaking in Ves Do Yes Do	tank below the operators? Yes No Cover Damage Yes No	ating depth o

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082