Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	t be completed in its entired	ty to constitute a v	alid maintenance	permit. This permit	must be complete	
Date of Maintenan	rforming maintenance activece: 5-29-19 Reason	on for Maintenance	Boutine	ition of the maintena	nce activity.	
Property Address:	360 Queenan	she S	Property Owner's I	Name: Cheryl. or	nd teith El	
Municipality: 40	Keland ZIP:55	043 Property Ide	entification Number	r:		
Maintenance Perm	it No: 9 168 115169	Maintainer Name a	nd License No. Pinl	ky's Environmental Se	wer Service/ L1673	
Mainte	enance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No	(if no provide measurements) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
evidence of da	re of tank leakage from a se maged, cracked, or structur Tank	Leaking Out	tenance hole cove	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No				
			☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
	Pretreatment Tank					
	Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank Pump Tank ns of septage were removed	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 /2 00	Pretreatment Tank Pump Tank as of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 /2 00	Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal concerns.	
Tank #1 /2 oc 5. Other informatio	Pretreatment Tank Pump Tank as of septage were removed gal Tank #2 an: List any troubleshooting	Yes No Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Atank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	concerns.	
Tank #1 /2 ox	Pretreatment Tank Pump Tank as of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No gal Pretreatment minor repairs con	Yes No Yes No Yes No Atank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001