

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety			11 12 11 12 11 12		
Date of Maintenance:	5.23-19 Reason	for Maintenance:	Routine			
	3035 Valley (			2.1	e Barton	
Municipality: 1		OO Property Ide				
Maintenance Permit N	10: <u>a1632-15241</u>	Maintainer Name ar	id License No. Pink	y's Environmental Sev	ver Service/ L167	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	of tank leakage from a se aged, cracked, or structur	ptic, holding, pretr			ating depth or	
	Septic/Holding Tank #1	☐ Yes ► No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed		tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other	concerns.	
6. Location of septage	e disposal:					
	Pinky	's Environmental Se				
		PO Box 35	4			

P: 651-439-4847 License Number: L1673

Afton MN 55001