

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

| This section must be co | ompleted in its entirety t | o constitute a vali | d maintenance per | mit. This permit n | nust be completed |
|---|---|--|---|--|--------------------|
| | ing maintenance activitie | | | | |
| Date of Maintenance: | - 8-19 Reason f | or Maintenance: _ | Routine | | |
| | 760 2041 St | | | | Bernardi |
| Municipality: Hasti | ngs ZIP: 5500 | 22Property Iden | tification Number: | | _ |
| | d3621m15170 Ma | | | | wer Service/ L1673 |
| | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank — in | | | |
| ☐ Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to remove | ve septage: Maintenand | e Hole Other (en | ter authorization code | e) Tankinfl | one gudeo |
| 2. Were all covers secu | rely replaced? 🗌 Yes 🗀 | No | | | |
| Is there evidence of evidence of damage | tank leakage from a septi ed, cracked, or structural | c, holding, pretre ly unsound mainte | atment or pump ta enance hole covers | ink below the opera $? \square$ Yes \square No | ating depth or |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| S | eptic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| Se | eptic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No . | ☐ Yes ☐ No | |
| P | retreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| P | ump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons of | septage were removed? | | | | |
| Tank #1 1500 g | gal Pretreatment t | ankgal | Pump Tank | gal | |
| 5. Other information: Li | ist any troubleshooting, n | ninor repairs cond | lucted, tank safety | concerns, or other | concerns. |
| | / | | | | |
| 6. Location of septage di | sposal: | No. 10 | | | 11 |
| | NC. | | | | |
| | | | | | |

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673