

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	6-27-19 Reason	for Maintenance:	Routino		
Property Address: 5	361 165#54 N	MN	Property Owner's N	ame: Dausel + D	orther Rove
Municipality: Hung	ZIP:550	38 Property Ide	ntification Number	:	
	: L 4057; 15802				2428
				ine o betwee believe	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes  No (if no provide measurements)		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sec</li><li>3. Is there evidence of</li></ul>	ove septage: Maintena curely replaced? Yes of tank leakage from a se ged, cracked, or structur	□ No ptic, holding, pret	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ৺No	☐ Yes →No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 750	of septage were removed gal Tank #2 List any troubleshooting disposal:	_ gal Pretreatmen			

Smilie's Sewer Service PO BOX 100

Scandia, MN 55073

License# 2428 P: 651-433-3934