

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

/ /	or Maintenance:	Routine		
Property Address: 13277 26th St. 7	7.	Property Owner's N	lame: Ron Pa	rish
Municipality: <u>A. Lakeland</u> ZIP: <u>5508</u>	2 Property Ide	ntification Number	:	
Maintenance Permit No: £5503s 10579 Ma				5
			tige 5	
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in		< in	
☐ Sludge and scum measured Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			0
☐ Yes ☐ No (if no provide measurements)				
1. Access used to remove septage: Maintenance	e Hole Mother (enter authorization c	ode)	
 Were all covers securely replaced? Yes \(\sum \text{No} \) Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 				
Tank	Leaking Out	Leaking In	Cover Damage]
		Leaking In		
Tank	Leaking Out	Leaking In	Cover Damage	
Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes Alo	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes ANO Yes ANO	Leaking In Yes No Yes No	Cover Damage Yes No	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1500 gal Tank #2 1000 gal 5. Other information: List any troubleshooting, not septage was a septage were removed?	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Pes No	gal
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1500 gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Pes No	gal

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162