

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	6-28-/ Reason 1	for Maintenance:	100 Ma	iht	
Property Address:	4411 136th S	+W	Property Owner's N	ame: /_arrv	Tenson
Municipality: 5416	Thater ZIP: 550	~1'	ntification Number		
	DATE INCOME				
Maintenance Permit N	0: 1/C/U/)007 W	aintainer Name ai	nd License No. Smil	ie's Sewer Service/L	2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greate			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
			enter authorization co	ode)	
	curely replaced? Yes				
3. Is there evidence of	of tank leakage from a sept	ic, holding, preti	eatment or pump	tank below the oper	rating depth or
evidence of dama	ged, cracked, or structura	lly unsound main	tenance hole cove	ers? Yes No	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank			□ v _{aa} □v _a	
	The second of th	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	- M-2-01 - COMMAND	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons			□ Yes □ No	□ Yes □ No	
	of septage were removed?				gal
Tank #1_/25(septage were removed?	gal Pretreatmen	t tank ga	al Pump Tank	
Tank #1_/25(of septage were removed?	gal Pretreatmen	t tank ga	al Pump Tank	
Tank #1_/25(septage were removed?	gal Pretreatmen	t tank ga	al Pump Tank	
Tank #1_/25(gal Tank #2 List any troubleshooting,	gal Pretreatmen	t tank ga	al Pump Tank	

Smilie's Sewer Service **PO BOX 100**

Scandia, MN 55073

License# 2428 P: 651-433-3934