## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: UB019019 Reason for Maintenance: <u>ROUTINE - JULING PROPERTY</u>						
Property Address (1994) Lthigh Rd Property Owner's Name: Ktilly VIPICENT						
Municipality: Hainnan zip: 1037 Property Identification Number:						
Maintenance Permit No: Mai	intainer Name and License No. L. hlimka Krylelf #2989					
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)					
Tank(s) Pumped	Liquid Level of Tank ———— in					
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in					
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater					

**1. Access used to remove septage:** 
Maintenance Hole Other (enter authorization code)

2. Were all covers securely replaced?  $\Box$  Yes  $\Box$  No

3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?  $\Box$  Yes  $\Box$  No

	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No	
	Septic/Holding Tank #2	🗌 Yes 🗌 No	🗌 Yes 🗌 No	🗌 Yes 🗌 No	
	Pretreatment Tank	🗌 Yes 🗌 No	🗌 Yes 🗌 No	🗌 Yes 🗌 No	
	Pump Tank	🗌 Yes 🗌 No	🗌 Yes 🗌 No	🗌 Yes 🛄 No	
4. How many gallons Tank #1 $\frac{12690}{12690}$	s of septage were removed εal Tank #2 1/2 20		tankga	al Pump Tank	gal
5. Other information	n: List any troubleshooting	, minor repairs cor 10 MH, DVI	nducted, tank safe MPLA MI	ty concerns, or othe	er concerns C
6. Location of septag	e disposal: Meth	)	· · · · · · · · · · · · · · · · · · ·		

Maintenance activities must be reported to the Department within 90 days.