



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

14949 62nd STREET NORTH P. O. BOX 6: STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

		on for Maintenance			
Property Address:	1200 Horan O	. NO	Property Owner's	Name: Kal Ha	nsel
Municipality: <u></u>		S090 Property Id			
Maintenance Permit	No: LIS20615986	Maintainer Name	and License No. Ok	on's Sewer Service/L2	16
		No. of the second secon			
želioka -	nedestation of the second and the se	Teams Mea	erake≜ae 1992 MYsanga nama a	1980-жылын айтын 11 жылынын Толык Т	(ती: अपसदस्ते
Tank(s) Rumped  Sludge and soum measured Do tanks need to be pumped?  Yes 1 No (If no provide measurements)		Studge & Scum / Liquid Level in Tarik, in Scum Level in Tarik, in Studge & Scum / Liquid Level X 100 = % Studge & Scum / Tariks must be pumped if 25% or greater			
	emove septage:  Mainte		Name of the last o		
<ol><li>Is there evidence</li></ol>	ecurely replaced?  Yes of tank leakage from a sinaged, cracked, or structularly	eptic, holding, pret	reatment or pump itenance hole cove Leaking in	tank below the opera	ting depth or
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes 🗓 No	☐ Yes ☑No	☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
٧.	Pump Tank	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes 🏳 No	
4 How many galland	s of septage were remove	<b>1?</b>	: tank ga	200	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082