

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	7-10-19 Reason	n for Maintenance:	Routia	r@		
Property Address: 🔼	885 182 nd St N	MN	Property Owner's N	lame: <u>5a// / /</u>	Dalluhn	
Municipality: May	ine ZIP: 550	2017 Property Ide	ntification Number	:		
	10: w6917a16199					
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes \(\sum \) No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: Maintenance Hole Mother (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes						
	Tank	Leaking Out	Leaking In	Cover Damage	1	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes XNo		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1200	of septage were removed gal Tank #2 : List any troubleshooting	_ gal Pretreatmen	t tank g nducted, tank safe	al Pump Tank ety concerns, or oth	gal ner concerns.	
6. Location of septage disposal: Law HPP/4						

Smilie's Sewer Service **PO BOX 100**

Scandia, MN 55073

License# 2428 P: 651-433-3934