

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity

Date of Maintenance:	8/16/18 Reason	on for Maintenance:	Partia	eron or the maniten	ance activity.	
Property Address:					Q. a	
	Hace House 50	500 WOG.	Property Owner's	Name: Marlo	- Drunel	
Municipality:	tage from ZIP: 55	2016 Property Ide	entification Numbe	r:	The state of the s	
Maintenance Permit I	10: h6386p12149	Maintainer Name a	nd License No	MSS-1915	_	
		-				
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)) = % studge & sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	move septage: Mainten	anco Holo Othor (
			enter authorization c	ode)		
3. Is there evidence	curely replaced? Yes	∟No				
evidence of dama	of tank leakage from a se aged, cracked, or structu	rally unsound main	reatment or pump tenance hole cove	tank below the ope ers?	erating depth or	
					1	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ✓ No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes No	☐ Yes ☐ No	☐ Yes ☑No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed	12				
Tank #1_/000	gal Tank #2 /000	u; gal Pretreatmont	tank	-l D		
. Other information:	List any troubleshooting	_ gat Tretreatment !. minor repairs cor	ducted tank safe	ty concerns or ath	gal	
Durch -	thry 41 ma	5	idacied, talik sale	cy concerns, or oth	er concerns.	
100	g g		7			
. Location of septage	disposal:					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162