

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

14949 62nd STREET NORTH P.O. BOXIGESTHUWATER, MN 55082-0006 Office: 651-430-6655 1777, 651-830-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on site for the duration of the maintenance activity.

N. LLOUGH ST. CO. T. LLOUGH	race entre e	and the second second		es continued France.	MOE HAND
Tank(s) Rumped Sludge and soum m Do tanks need to t	néasured be ou maed?	Strove Levelii	Tonk 1200 to	n 5 Scum Level in Tank. Level x 100	, í
U Yes U No (If i	no provide measurement		cum ii	anks must be pumped i	if 25% or gr
		THE RESERVE AND PERSONS NAMED IN COLUMN 2 IS NOT THE OWNER, THE OW	5° - ° ° ° ° 1 3 4° 0 ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °	777	-
ccess used to rem	nove sentage of Mainta	nones Mala TT Outs	Parada a chara a and a ser	4.40. 4	
	nove septage: Mainte		(enter authorization	code)	
			(enter authorization	cóđe)	
ere all covers sec	curely replaced? 🖾 Ye	s 🗆 No	E .		
ere all covers sec there evidence o	curely replaced? 🖾 Ye	S ONo eptic, holding, pre	roatmont he number	tönk holov the man	ating dent
ere all covers sec there evidence o	curely replaced? 🖾 Ye	S ONo eptic, holding, pre	roatmont he number	tönk holov the man	ating dept
ere all covers sec there evidence o	curely replaced? (S) Ye of cank leakage from a s ged, cracked, or struct	s 🗆 No eptic, holding, ore urally unsound mai	roatmont he number	tönk holov the man	ating depti
/ere all covers sec there evidence of evidence of dama	curely replaced? (S) Ye of tank leakage from a s ged, cracked, or struct Tank	S ONo eptic, holding, pre	roatmont he number	tönk holov the man	ating depti
/ere all covers sec there evidence of evidence of dama	curely replaced? (S) Ye of cank leakage from a s ged, cracked, or struct	s 🗆 No eptic, holding, ore urally unsound mai	reatment or pump ntenance hole cov	o tank below the opera ers?	ating depti
ere all covers sec there evidence of evidence of dama	curely replaced? (S) Ye of tank leakage from a s ged, cracked, or struct Tank	s 🗆 No eptic, holding, ore urally unsound mai Leaking Out	ireatment or pump ntenance hoje cov teaking in	o tank below the opera ers?	ating dept
ere all covers sec there evidence of evidence of dama	curely replaced? (S) Ye of tank leakage from a s ged, cracked, or struct Tank Septic/Holding Tank #1	s ONo eptic, holding, pre- urally unsound mai  Leaking but  OYes ONo	treatment or pump ntenance hole cov teaking in Ves No	Cover Damage  Yes No  Yes No  Yes No  Yes No	ating depti
Pere all covers sec there eyidence of evidence of dama	curely replaced? (S) Ye of tank leakage from a s ged, cracked, or structo  Tenk  Septic/Holding Tank #1  Septic/Holding Tank #2	s ONo eptic, holding, pre urally unsound mai  Leaking Dut O Yes ONo O Yes ONo	treatment or pump ntenance hole cov teaking in Ves No	cover Damage  Yes No	ating depti

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082