## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 11-12-15 Re	eason for Mainte	enance:	20utine	_		
Property Address: 3898 Leon	on Aug	Proper	ty Owner's Name:	Ron	Robinet	te
Municipality: Lake Elmo	State /	Zip Code	GEC	) Code/Pro	operty I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)				
<ul><li>☐ Tank(s) Pumped</li><li>☐ Sludge and scum measured.</li><li>Do tanks need to be pumped?</li><li>☐ Yes</li><li>☐ No (If no provide measured)</li></ul>	Tota	Liquid Level of Tank in. Sludge Level in. Scum Level in.  Total (Sludge + Scum) / Liquid Level = % Sludge & Scum in.				
* Tank must be pumped if this value is greater than 25%.						
2. If maintenance hole was used, were all	covers securely	replaced?	Yes No please		3	
Explanation:			- Halley - State - Control			
3. If owner refuses to allow a Subsurfa them complete and sign the following	ce Sewage Treange statement:	atment System	(SSTS) to be pump	ed throug	gh the maintenance	hole, have
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance						
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.						
4. Is the tank designed as a leaky tank? e.	xample: seepage	e pit, cesspool, di	ywell, leaching pit			
Tank#1 Yes No Verificatio	Method Used:		#			
Tank#2	– :Method Used					
5. Is there evidence of tank leakage from	_	olding, pretrea	ment or pump tan	k below th	ne operating depth o	or evidence of
damaged, cracked, or structurally unsound maintenance hole covers?						
Tank	Lea	king Out	Leaking In		Cover Damage	
Septic/Holding Tank	#1	es No	Yes No		☐ Yes ☐ No	
Septic/Holding Tank	#2 <b> </b>	es $\Gamma$ No	Yes No		☐ Yes ☐ No	
Pretreatment Tank	ГΥ	es $\Gamma$ No	☐ Yes ☐ No		☐ Yes ☐ No	<u> </u>
Pump Tank	Г	es $\Gamma$ No	☐ Yes ☐ No		☐ Yes ☐ No	
6. How many gallons of septage were	removed?					
Tank #1 1500 Tank #2		Pretreatment Tank Pu		Pump	ump Tank	
7. Other information: List any trouble	shooting, min	or repairs cond	lucted, tank safety	concerns,	or other concerns.	
8. Certification: I hereby certify as a St and made the observ	ate of Minneso	ly supervised of	thers in the performa	ance of this	s job.	
Maintainer's Name: PINKY'S SEWER	SERVICE	Maintair	er's Address: P.O. Bo	ox 354 Afto	on, MN 55001	
Maintainer's License #: 1673	Maintainer's/P	hone #: 651-4:	39-4847			
Maintainer's Signature / W/W Date: 11-12-15						