

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be | e completed in its entirety | to constitute a v | alid maintenance | permit. This permit | must be completed | |
|----------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|---------------------|--|
| <u>prior</u> to perfo | orming maintenance activit | ies and remain o | n-site for the dura | tion of the maintena | ince activity. | |
| Date of Maintenance | 6-19-19 Reason | for Maintenance: | Rativa | | ,, | |
| Property Address: 🔟 | | | Historian Control of the Control of | Name: Kim E | ricksen | |
| Municipality: St | illucator zip:550 | XZ Property Ide | entification Number | r: | | |
| | 40: h7918p 13373A | | | | 2 | |
| | 11100.001 | name name a | ild License No. Pini | ky's Environmental Se | ewer Service/ L1673 | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | | |
| Tank(s) Pumped | | Liquid Level of | Liquid Level of Tank ——— in | | | |
| \square Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | | |
| 1. Access used to rer | move septage: Maintenan | nce Hole Other (| enter authorization c | ode) | | |
| | curely replaced? Yes | | | | | |
| 3. Is there evidence | of tank leakage from a sept | tic, holding, pret | reatment or pump | tank below the oper | rating depth or | |
| evidence of dama | aged, cracked, or structura | ally unsound main | tenance hole cove | ers? 🗆 Yes 🖹 No | amig depth of | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | | | | | |
| | . Total detirione Tallik | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank of septage were removed? | ☐ Yes ☐ No | | | | |
| Tank #1 <u>/500</u> | Pump Tank of septage were removed? gal Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | Yes No | gal | |
| Tank #1 <u>/500</u> 5. Other information: | Pump Tank of septage were removed? gal Tank #2 List any troubleshooting, | ☐ Yes ☐ No | ☐ Yes ☐ No | Yes No | gal r concerns. | |
| Tank #1 <u>/500</u> 5. Other information: | Pump Tank of septage were removed? gal Tank #2 List any troubleshooting, | ☐ Yes ☐ No gal Pretreatment minor repairs cor | Yes No | Yes No al Pump Tank ty concerns, or othe | r concerns. | |
| 5. Other information: Mashale una | Pump Tank of septage were removed? gal Tank #2 List any troubleshooting, Mer Sidewalk | ☐ Yes ☐ No gal Pretreatment minor repairs cor | Yes No tank ganducted, tank safe | ☐ Yes ☐ No al Pump Tank ty concerns, or other | r concerns. | |
| 5. Other information: Mashale una | Pump Tank of septage were removed? gal Tank #2 List any troubleshooting, Mer Sidewalk | ☐ Yes ☐ No gal Pretreatment minor repairs cor | Yes No tank ganducted, tank safe | ☐ Yes ☐ No al Pump Tank ty concerns, or other | r concerns. | |
| 5. Other information: Mashale una | Pump Tank of septage were removed? gal Tank #2 List any troubleshooting, Mer Sidewalk | ☐ Yes ☐ No gal Pretreatment minor repairs cor | Yes No tank ganducted, tank safe | ☐ Yes ☐ No al Pump Tank ty concerns, or other | r concerns. | |

nental Sewer Service Inc.

PO Box 354

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.