

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety t	o constitute a v	alid maintenance	permit. This permit	must be completed
<u>prior</u> to performing maintenance activitie	es and remain o	n-site for the dura	tion of the maintena	ance activity.
Date of Maintenance: $(0-1)^{2}-19$ Reason f	or Maintenance:	Ratin	Λ	
Property Address: 15880 151 51	Sc	Property Owner's I	Name: Why (Puolel n
Municipality: After zip5500	å.	entification Numbe		
Maintenance Permit No: <u>\\\4719 L15612</u> Ma				ower Sender / 14672
			ky 3 Environmentat 36	ewer Service/ L16/3
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Tank — in		
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance	e Hole Other			
2. Were all covers securely replaced? 🗹 Yes 🗆		200000000000000000000000000000000000000	ode	
3. Is there evidence of tank leakage from a seption		reatment or numn	tank halatl	
evidence of damaged, cracked, or structurall	y unsound mair	itenance hole cove	ers? Yes No	rating depth or
Tank	W. ASSER			
	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes ☑ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 15 co gal Tank #2gal	al Pretreatment	tankga	al Pump Tank	gal
Other information: List any troubleshooting, m	inor repairs cor	nducted, tank safe	ty concerns, or othe	r concerns.
		1		
Location of contago disposal.				
. Location of septage disposal:				
Pinla/a F	nvironmental C-	wer Service Inc.		
Filliny 5 L	PO Box 35			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001