

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be seemed to be				Tarree I Ci IIIIC
This section must be completed in its entirety prior to performing maintenance activities	to constitute a view and remain a	valid maintenance	permit. This permit	must be completed
Date of Maintenance: 6-17-19 Reason	for Maintenance	Routine	ition of the maintena	ance activity.
Property Address: 819 Neal Ave A	r .		Name: Robert	fild brong life
MunicipalityStillwater zIP: 550		entification Number	r.	"HebranaT
Maintenance Permit No: 4634 OW 18622 M	aintainer Name	and License No. Dist		
See La	Traine I	and License No. Pini	ky's Environmental Se	ewer Service/ L1673
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank ——— in			
$\square$ Sludge and scum measured	Sludge Level in Tank in			
Do tanks need to be pumped?	Sludgo + Scum			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance			nast be pumped	11 25% or greater
2. Were all covers securely replaced?  Yes		enter authorization co	ode)	
3. Is there evidence of tank lookage from a visit	I NO			
3. Is there evidence of tank leakage from a septi	ic, holding, pret	reatment or pump	tank below the oper	ating depth or
evidence of damaged, cracked, or structural	ly unsound mair	itenance hole cove	rs? Yes No	
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ Ho	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 /250 gal Tank #2 /250 g	al Pretreatment	tank ga	I Dump Tank	
o. Other information: List any troubleshooting, m	ninor repairs con	ducted tank safet	C Fullip Talik	gal
		idacted, talk salet	y concerns, or other	concerns.
. Location of septage disposal:				
Pinky's E	invironmental Se	wer Service Inc		
	PO Box 35			
Afton MN 55001				

Maintenance activities must be reported to the Department within 90 days.