Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 6-7-19 Reason for Maintenance: Reason for Maintenance					
Property Address: 1784 Stagecouch TILS. Property Owner's Name: Charles Brower					
Municipality: 174 ZIP: 5500 Property Identification Number:					
Maintenance Permit No: 10121 15384 Maintainer Name and License No. Pinky's Environmental Sewer Service/ L1673					
maintainer Hame and Electise No. Flinky's Environmental Sewer Service/ L1673					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code) Top DIA					
2. Were all covers securely replaced? ☐ Yes ☐ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 1500 gal Tank #2gal Pretreatment tankgal Pump Tankgal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
			115 15 11 11 11 11 11 11 11 11 11 11 11	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		/			
b. Location of septage disposal:St_/a					
Pinky's Environmental Sewer Service Inc.					

PO Box 354

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.