

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

|  |   |   |                          | The state of the s |  |
|--|---|---|--------------------------|--|--|
| This section must be completed in its entirety prior to performing maintenance activity                      | to constitute a v   | alid maintenance                              | permit. This permit      | must be completed  |  |
| Date of Maintenance: $0.7 - (9)$ Reason  | for Maintenance:  | Boutine                                       |                          |  |  |
| Property Address: 1520 110th St N Property Owner's Name: St Croix Ballet                                     |   |   |                          |  |  |
| A  |   | entification Number                           |                          |  |  |
| Maintenance Permit No: 41942d15186   |   |   |                          | wer Service / L1672  |  |
| J  |   |   | y o zavii omnemat se     | Well Delvice/ E10/3  |  |
| Maintenance Performed  | ed Tank Measurement (must be completed if tanks NOT pumped) |   |                          |  |  |
| Tank(s) Pumped   | Liquid Level of   | Liquid Level of Tank — in                     |                          |  |  |
| ☐ Sludge and scum measured   | Sludge Level in   | Sludge Level in Tank in Scum Level in Tank in |                          |  |  |
| Do tanks need to be pumped?  | Sludge + Scum / Liquid Level X 100                          |   |                          |  |  |
| $\square$ Yes $\square$ No (if no provide measurements)  | = % Sludge & Scum Tanks must be pumped if 25% or greater    |   |                          |  |  |
| 1. Access used to remove septage: Maintena   | nce Hole Other (  | enter authorization c                         | odo) testa en oc         |  |  |
| 2. Were all covers securely replaced? Yes  | □ No.   | addionization c                               | ac) 700 all              | P  |  |
|  |   |   |                          |  |  |
| <ol><li>Is there evidence of tank leakage from a sep<br/>evidence of damaged, cracked, or structur</li></ol> | ally upsound main   | reatment or pump                              | tank below the oper      | ating depth or   |  |
|  | any unsound mair  | itenance note cove                            | ers! L Yes No            |  |  |
| Tank   | Leaking Out   | Leaking In                                    | Cover Damage             |  |  |
| Septic/Holding Tank #1   | ☐ Yes ☑No   | ☐ Yes ☑No                                     | ☐ Yes ☑ No               |  |  |
| Septic/Holding Tank #2   | ☐ Yes ☑ No  | ☐ Yes ☑ No                                    | ☐ Yes ☑ No               |  |  |
| Pretreatment Tank  | ☐ Yes ☐ No  | ☐ Yes ☐ No                                    | ☐ Yes ☐ No               |  |  |
| Pump Tank  | ☐ Yes ☐ No  | ☐ Yes ☐ No                                    | ☐ Yes ☐ No               |  |  |
| 4. How many gallons of septage were removed?   |   |   |                          |  |  |
| Tank #1 $1250$ gal Tank #2 $1000$  | gal Pretreatment  | tankga  | al Pump Tank             | gal  |  |
| 5. Other information: List any troubleshooting,  | minor repairs cor   | nducted, tank safe                            | ty concerns or other     | Concerns   |  |
|  |   |   | s, series ins, or series | concerns.  |  |
|  |   |   |                          |  |  |
| . Location of septage disposal: SL pag   | 1   |   |                          |  |  |
| 1 - 1  |   |   |                          |  |  |
| Pinky's Environmental Sewer Service Inc.   |   |   |                          |  |  |
| PO Box 354   |   |   |                          |  |  |

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673