

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be				bystem Mainter		
prior to port	oe completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be completed	
	or maniferiance activ	ities and remain o	n-site for the dur-	tion of the	nce activity.	
Date of Maintenance	Reason Reason	n for Maintenance:	Routin	ne	and allies or a same of the	
Property Address: 2	30 Quant Ct	S	Property Owner's	1 0	loughto' -	
Municipality: Lak	eland zip:550	Property Ide	entification Numbe	r:	iermaier	
Maintenance Permit	No: 13351414793	Maintainer Name a	nd License No. Pin	ky's Environmental Se	 wer Service/ L1673	
				Translation (
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (it	f no provide measurements) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintena	ance Hole Other	enter authorization o	ode) Tankin	P)	
2. Were all covers se	ecurely replaced? Yes	□ No	authorization c	ode) / un con	- Due gos	
3. Is there evidence	of tank leakage from a so	otic bolding				
evidence of dam	of tank leakage from a se aged, cracked, or structur	ally unsound main	tenance by	tank below the opera	ating depth or	
		any ansound main	teriance note cove	rs? Yes No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
Septic/Holding Tank #2 Pretreatment Tank Pump Tank		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons	of septage were removed	?				
Tank #1 1500	_ gal Tank #2	gal Pretreatment	tank ga	I Pump Tank		
5. Other information:	List any troubleshooting,	minor repairs con	ducted, tank safet	V CODCOTOS OF other	gat	
			and a sure	y concerns, or other	concerns.	
			5 11			
6. Location of septage	disposal: Str					
	Pinkv's	Environmental Sev	ver Service Inc			
		PO Box 354				
		. O DOX 334	<u> </u>			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001