

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9/25/18 Reason	for Maintenance:	ROUTIN		and didivicy.
Property Address: _/	The state of the s	10			1.1
	£ 1		Property Owner's I	Name: <u>Maylor</u>	forbust
Municipality:	rytown ZIP:5506	2 Property Ide	entification Number	:	
Maintenance Permit N	10:01909v 12947 A	Maintainer Name a	nd License No. M	155- L915	
			Antheadepassed		ang philipping and service and a copy of the production in the contract of the desired and
		1			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements)					
1. Access used to rer	move septage:	So Holo Klothor (Huelik t	5 / · · · · · · · /
			enter authorization c	ode, Unicerz (O LOCAR MANA
2. Were all covers se	curely replaced? Yes	∟ No			
evidence of dama	of tank leakage from a sep aged, cracked, or structura	tic, holding, pret ally unsound main	reatment or pump Itenance hole cove	tank below the ope	erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	y x
*	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ❷No	☐ Yes 🔁 No.	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ❷No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
A How many gallons	of septage were removed?				•
5 Other information	gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank	gal
- Junet antormation	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.
					THE PART THE SECONDARY AND COMPANY OF THE PART T
Location of septage	disposal:				

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162