

Date of Maintenance: 8-9-19

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

Routine

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Property Address: 10 / Stone B	volge Trl Property Owner's Name: Richard M	lautins
	550 82 Property Identification Number:	
Maintenance Permit No: g 7 100 0163	Maintainer Name and License No. Smilie's Sewer Service/L2428	
Maintenance Performed	Tank Measurement (must be completed if tanks NOT	pumped)
 ✓ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measure) 	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 259 ments)	
1. Access used to remove septage: M	intenance Hole Other (enter authorization code)	
2. Were all covers securely replaced?		
3. Is there evidence of tank leakage from	a septic, holding, pretreatment or pump tank below the operating fucturally unsound maintenance hole covers? Yes No Leaking Out Leaking In Cover Damage	g depth or
3. Is there evidence of tank leakage from evidence of damaged, cracked, or st	a septic, holding, pretreatment or pump tank below the operating fucturally unsound maintenance hole covers? Yes No Leaking Out Leaking In Cover Damage	g depth or
3. Is there evidence of tank leakage from evidence of damaged, cracked, or st	Leaking Out Leaking In Yes No Yes No Yes No Yes No Yes No Yes No	g depth or
3. Is there evidence of tank leakage from evidence of damaged, cracked, or st Tank Septic/Holding Tank	Leaking Out Leaking In Yes No Yes No Yes No Yes No Yes No Yes No	g depth or
3. Is there evidence of tank leakage from evidence of damaged, cracked, or st Tank Septic/Holding Tank Septic/Holding Tank	Leaking Out Leaking In Cover Damage 1 Yes No Yes No Yes No Yes No	g depth or

Smilie's Sewer Service **PO BOX 100**

Scandia, MN 55073

License# 2428 P: 651-433-3934