

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	8-2-19 Reason	for Maintenance:	Routing	0	
Property Address: <u>(</u>	320154th54 N	MIU	Property Owner's N	ame: Greg S	eitz
Municipality: Maria			ntification Number		
Maintenance Permit N	0: +9173K16495 N				2428
					
		T			NOT
Maintena	nce Performed	Tank Measurement (must be completed if tanks NOT pumped)			
'∰Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		studge + scum / Equid Level \times 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
Yes \square No (if no provide measurements)					
Access used to ren	nove septage: Amaintenar	nce Hole Other (6	enter authorization c	ode) (in 10 if	4
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or 					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes					
			Contraction of the Contraction o		
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	Yes K No	☐ Yes ♥No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. Harrison as Harri					
4. How many gallons of septage were removed? Tank #1 2 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
1/0/1/15					
	10	0100	1001		
6. Location of septage disposal:					
			. /		
			/		

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934