


Additional Soil Observation Logs



Project ID: 0

Client: Joe Fleming Location / Address: 5040 Lake Elmo Ave N Lake Elmo

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation: Grass Soil survey map units: Slope %: Elevation: 08/09/19

Weather Conditions/Time of Day: Sunny Afternoon Date: 08/09/19

Observation #/Location: Soil boring #2 Observation Type: Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape		Consistence
							Shape	Grade	
0-8"	Loamy Sand	<35%	7.5YR 3/4				Granular	Weak	Friable
8-30"	Fine Sand	<35%	7.5YR 4/6				Single grain	Weak	Loose
30-52"	Sand	<35%	7.5YR 4/4				Granular	Weak	Loose

Comments