

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit m	nust be completed
prior to performing maintenance activit	ties and remain on	-site for the durat	ion of the maintenan	ce activity.
Date of Maintenance: 5 - D-16 Reason	for Maintenance:	2cutine		
Property Address: 12245 72nd S	t. Mu.	Property Owner's N	ame: Jim P	eterson
Municipality: We Elmo ZIP: 550	M2 Property Ide	ntification Number:		
Maintenance Permit No: 17893C1339	Maintainer Name a	nd License No. P	Mrey 167	3
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a sequidence of damaged, cracked, or structure Tank 	ptic, holding, pret	reatment or pump tenance hole cove	tank below the operers? Cover Damage	ating depth or
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed	1?			
Tank #1 / O Sal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.

Maintenance activities must be reported to the Department within 90 days.