



Additional Soil Observation Logs

Project ID:

Client: **Debbie Aster** Location / Address: **13304 122nd Street South Hastings, MN**

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation: **Lawn** Soil survey map units: Slope %: Elevation (ft):

Weather Conditions/Time of Day: **Sunny 4:00 P.M.** Date: **08/14/19**

Observation #/Location: Soil boring #4 Observation Type: **Auger**

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence
0-16"	Loam	<35%	7.5YR 4/6				Granular	Weak	Friable
16-36"	Loam	<35%	7.5YR 5/8				Granular	Weak	Friable
36-60"	Silty Clay Loam	<35%	7.5YR 5/8				Granular	Weak	Friable

Comments