



# Soil Observation Log

Project ID: v 04.01.2019

<b>Client:</b> Debbie Aster		Location / Address: 13304 122nd Street South Hastings, MN							
Soil parent material(s): (Check all that apply)									
<input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter									
Landscape Position: (check one)									
<input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope    Slope shape									
Vegetation: Lawn		Soil survey map units: _____							
Weather Conditions/Time of Day: Sunny 4:00 P.M.		Date: 08/14/19							
<b>Observation #/Location:</b> Soil Boring #3									
<b>Observation Type:</b> Auger									
Depth (In)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence
0-18"	Loam	<35%	7.5YR 4/6				Granular	Weak	Friable
18-36"	Loam	<35%	7.5YR 5/8				Granular	Weak	Friable
36-60"	Silt Loam	<35%	7.5YR 5/8				Granular	Weak	Friable
Comments									