

Additional Soil Observation Logs

Project ID: 0

Client: Debbie Aster		Location / Address: 13304 122nd Street South Hastings, MN							
Soil parent material(s): (Check all that apply) <input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter									
Landscape Position: (check one) <input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope <input type="checkbox"/> Slope shape									
Vegetation:	Lawn	Soil survey map units:		Slope %:	Elevation:				
Weather Conditions/Time of Day:		Sunny 4:00 P.M.		Date:	08/14/19				
Observation #/Location:		Soil Boring #2							
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence
0-18"	Loam	<35%	10YR 4/6				Granular	Weak	Friable
18-32"	Loam	<35%	10YR 5/8				Granular	Weak	Friable
32-54"	Loam	<35%	7.5YR 5/8				Granular	Weak	Friable
54-60"	Silt Loam	<35%	7.5YR 4/6				Granular	Weak	Friable
Comments									