

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

I was assessed in the combleted in its buttle	ty to constitute a v	alid maintanana			
This section must be completed in its entire prior to performing maintenance activ	ities and remain o	and maintenance	permit. This permit	must be complet	
			tion of the maintena	ance activity.	
1000	on for Maintenance:		1		
Property Address: 1390 Quusav	Ct. Sc.	Property Owner's I	Name: Mann	CO. 1000	
	M3Property Ide				
Maintenance Permit No: X2663n15589					
	manifed Hame a	nd License No. Pini	ky's Environmental Se	ewer Service/ L16	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level in Tank in Scum Level in Tank in Sludge + Scum			
\square Yes \square No (if no provide measurements	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of tank leakage from a se	ptic, holding preti	eatment or nump			
evidence of damaged, cracked, or structu	rally unsound main	tenance hole cove	rs? Yes No	rating depth or	
Tank	rally unsound main	tenance hole cove	ers? Yes No Cover Damage	rating depth or	
evidence of damaged, cracked, or structu	rally unsound main	tenance hole cove	rs? Yes No	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage	rating depth or	
Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes Ano	rating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No	rating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed Tank #1 (Occo gal Tank #2 (Coco gal Tank #2 (Leaking Out Yes No	Leaking In Yes No Yes No Yes No Yes No And Yes No And Yes No And Yes And And Yes	Cover Damage Yes No Yes No Yes No Yes No	gal r concerns.	

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673