

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	ne completed in its anticat	v to constitut			nance remine	
prior to perf	e completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	t must be complete	
	orming maintenance activ			tion of the mainten	ance activity.	
Date of Maintenance	e: _/_ Reaso	n for Maintenance:	Reutin	e		
Property Address: 3	160 manning	Arc Sc	Property Owner's I	Name: Francis	Cenike	
Municipality: <u>UV</u>	UDM ZIPEST	25 Property Ide	entification Numbe	r:		
Maintenance Permit	No: @ 2527 pl6081					
	10.000111001	maintainer name a	nd License No. Pin	ky's Environmental S	ewer Service/ L167	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum			
☐ Yes ☐ No (ii	f no provide measurements		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1 Access used to re	move centage.				a ii 25% oi greater	
	move septage: Maintena		enter authorization c	ode)		
	ecurely replaced? Yes					
3. Is there evidence	of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the ope	erating depth or	
evidence of dam	aged, cracked, or structu	rally unsound main	tenance hole cove	ers? 🗌 Yes 🗷 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	•	
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes ☑No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 050	gal Tank #2 <u>650</u>	gal Pretreatment	tank g	al Pump Tank	I	
. Other information	: List any troubleshooting	minor repairs cor	ducted tank safe	ty concerns or all	gat	
		,or repuirs cor	iducted, talk sale	ty concerns, or other	er concerns.	
U a Un						
. Location of septage	e disposal: St pag 1				_	
			The state of the s			
	Pinky*	s Environmental Se	wer Service Inc			
	i iliky	PO Box 35				
		PU DUX 35	4			

Afton MN 55001

P: 651-439-4847 License Number: L1673