## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance	9-15 Reason for	Maintena	ance:	outin	l			
Property Address: 108	7 Manning	Ave n	Yeroperty C	Owner's Name:	Jan	LA L	31	
Municipality:	e Elme s	tate M	Zip Code _	GI	EO Code/Proper	ty I.D. #:	2	
What was done	to the system?		Tank Measure	ements (must l	oe completed if	tanks NOT p	oumped)	
Tank(s) Pumped  Sludge and scum measured.  Do tanks need to be pumped?  Yes No (If no provide measurements)		Liquid Level of Tank in. Sludge Level  Total (Sludge + Scum) / Liquid Level			id Level	in. Scum I - = % Sludge	 e & Scum 	
1. Access used to remove	septage: Maintena	nce Hole	Other (Go to	o #3 below)		must be pume eater than 25%	nped if this value	
2. If maintenance hole wa	s used, were all covers s	ecurely re	eplaced? 🏂 Ye	s 🗌 No <b>pleas</b>		tater than 25	70.	
Explanation:								
3. If owner refuses to allo them complete and sig			nent System (SS	STS) to be pum	ped through tl	he maintenai	nce hole, have	
I,	(owr	ner's nam	e), refuse to allo	w the removal	of solids and liqu	uids through t	the maintenance	
hole. I understand that	removal of solids and lie	quids thro	ough other acces	ss points is not	considered mair	ntenance.		
4. Is the tank designed as	a leaky tank? example: s	eepage pi	t, cesspool, drywe	ell, leaching pit				
Tank#1 Yes No	o Verificatio Method U	sed:						
Tank#2   Yes   No	o Verificatio Method U	Ised:						
5. Is there evidence of ta damaged, cracked, or	ınk leakage from a sep	tic, holdi			nk below the o	perating dep	oth or evidence of	
damagea, crackea, or	Tank		Leaking Out		Cov	Cover Damage		
Septic	/Holding Tank #1		No	☐ Yes   N	о Г	Yes No		
3	/Holding Tank #2	☐ Yes	T No	☐ Yes ☐ N	о Г	Yes   No		
Pretrea	atment Tank	Yes	Г No	☐ Yes ☐ N	о Г	Yes No	*	
Pump	Tank	Yes	Г No	☐ Yes ☐ N	о Г,	Yes No		
6. How many gallons of	septage were removed	1?	<u> </u>					
Tank #1 1500 Tank #2			Pretreatment Tank			Pump Tank		
7. Other information: Li	st any troubleshooting	j, minor r	epairs conduct	ed, tank safet	y concerns, or o	other concerr	15.	
8. Certification: Thereby and ma	y certify as a State of Minde the observations, or	nnesota c directly s	ertified SSTS Ma upervised other	intainer that I p s in the perforn	personally condunance of this job	ucted the wor	k	
Maintainer's Name: Pl	NKY'S SEWER SERVICE		Maintainer's —	Address: P.O. E	Box 354 Afton, M	1N 55001		
Maintainer's License #			ne #: 651-439-4	847				
Maintainer's Signature	Alla	~		Dat	e: 1297	1		