

SSTS MAINTENANCE REPORT

Date of Maintenance 12-1-15 Reason for Maintenance: Routine
 Property Address: 420 Quality Ave N Property Owner's Name: Bryan EK
 Municipality: Lakeland State MN Zip Code _____ GEO Code/Property I.D. #: _____

| What was done to the system? | Tank Measurements (must be completed if tanks NOT pumped) |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Tank(s) Pumped <input type="checkbox"/> Sludge and scum measured. Do tanks need to be pumped? <input type="checkbox"/> Yes <input type="checkbox"/> No (If no provide measurements) | Liquid Level of Tank _____ in. Sludge Level _____ in. Scum Level _____ in. Total (Sludge + Scum) _____ / Liquid Level _____ = % Sludge & Scum _____ * |

1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.
2. If maintenance hole was used, were all covers securely replaced? Yes No **please explain**

Explanation: _____

3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:

I, _____ (owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.

4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit

Tank#1 Yes No Verificatio Method Used: _____
 Tank#2 Yes No Verificatio Method Used: _____

5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?

| Tank | Leaking Out | Leaking In | Cover Damage |
|------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|
| Septic/Holding Tank #1 | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Septic/Holding Tank #2 | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Pretreatment Tank | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Pump Tank | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input type="checkbox"/> No |

6. How many gallons of septage were removed?

Tank #1 1000 Tank #2 1000 Pretreatment Tank _____ Pump Tank _____

7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001

Maintainer's License #: 1673 Maintainer's Phone #: 651-439-4847

Maintainer's Signature: [Signature] Date: 12-1-15