

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| | mining maintenance activiti | es and remain on | Site for the durat | ion of the maintena | ince activity. |
|---|---|--|--------------------------------|--------------------------------------|---------------------|
| | 8-14-19 Reason | | | | |
| Property Address: <u>10</u> | 239 209/4 ST N | MN | Property Owner's N | ame: John So | chree Keis |
| | + Lake ZIP: 550 | | | | |
| | 0: L6414:6825 N | | | | .2428 |
| | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes \(\sum \) No (if no provide measurements) | | Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to remove septage: Maintenance Hole Sother (enter authorization code) Gin pipe | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No Tank Leaking Out Leaking In Cover Damage | | | | | |
| | | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes → Yo | ☐ Yes No | ☐ Yes ☐ No | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | , |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| Tank #1_1,250 | of septage were removed? gal Tank #2 List any troubleshooting, disposal: | gal Pretreatmen | t tank——— ganducted, tank safe | al Pump Tank ety concerns, or oth | gal er concerns, |

Smilie's Sewer Service PO BOX 100

Scandia, MN 55073

License# 2428 P: 651-433-3934