



Soil Observation Log

Project ID: v 04.01.2019

Client: **Judy Larson** Location / Address: **6786 St. Croix Trail**

Soil parent material(s): (Check all that apply) Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one) Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape _____

Vegetation: **Lawn** Soil survey map units: _____ Slope %: _____ Elevation: _____

Weather Conditions/Time of Day: **Sunny Afternoon** Date **09/01/19**

Observation #/Location: **2' from STA** Observation Type: **Auger**

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure-----		
							Shape	Grade	Consistence
0-6"	Loamy Sand	<35%	10YR 3/3				Granular	Weak	Friable
6-24"	Loamy Fine Sand	<35%	10YR 5/8				Single grain	Weak	Loose
24-36"	Loamy Sand	<35%	7.5YR 5/4				Single grain	Weak	Loose
36-52"	Loamy Sand	<35%	7.5YR 4/6				Granular	Weak	Loose

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Shelley Schloantz (Designer/Inspector) 1106 (License #) 9/1/19 (Date)