


Soil Observation Log

Project ID: v 04.01.2019

Client: William Dunbar		Location / Address: 6777 Lamar Ave S Cottage Grove							
Soil parent material(s): (Check all that apply)									
<input type="checkbox"/> Outwash	<input type="checkbox"/> Lacustrine	<input checked="" type="checkbox"/> Loess	<input type="checkbox"/> Bedrock						
<input type="checkbox"/> Summit	<input checked="" type="checkbox"/> Shoulder	<input type="checkbox"/> Alluvium	<input type="checkbox"/> Organic Matter						
Landscape Position: (check one)		<input type="checkbox"/> Foot Slope	<input type="checkbox"/> Toe Slope						
<input checked="" type="checkbox"/> Lawn	Soil survey map units: 11.0		Slope shape: Linear, Convex						
Vegetation:		Slope %:	Elevation:						
Weather Conditions/Time of Day: Cold - Party Cloud		Date:	01/29/20						
Observation #/Location: 1" outside of STA - marked on map		Observation Type: Auger							
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence
0-6"	Loam	<35%							
6-36"	Silt Loam	<35%	10YR 3/3						
36-56"	Silt Loam	<35%	10YR 4/4						
56-72"	Fine Sandy Loam	<35%	10YR 4/3						
Comments									

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

S. Schlomka
(Designer/Inspector)


(Signature)

1106
(License #)

1/29/2020
(Date)