



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration

	son for Maintenance	e: Recular			
Property Address: 8980 180° St	N,	- 7	s Name: Joyce	Malinela	
Municipality: Forest Lake ZIP: 5 Maintenance Permit No: W1285e9692	Property I Maintainer Name	dentification Numb	per:		
Maintenance Performed	Tank Me	Tank Measurement (must be completed if tanks NOT pumped			
 ☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurement) 	Sludge Level in Sludge + Scum	/ Liquid	n Scum Level in Tan Level X 10 anks must be pumpe	00	
Access used to remove septage: Maintel Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	s No eptic, holding, pret urally unsound main	reatment or pump		erating depth or	
Tank	Leaking Out	Leaking In	Cover Damage	1	
Septic/Holding Tank #1	☐ Yes ☒No				
Joseph Moraling Tallik #1	☐ Yes ☒No	Yes No	☐ Yes ⋈ No	,	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☒ No ☐ Yes ☐ No	i L	
	-	_			
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2 Pretreatment Tank	Yes No Yes No Yes No Yes No gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal r concerns.	