

SSTS MAINTENANCE REPORT

System Location

Address 15525 st Croix tr n		Telephone Number	6514332486
City Marine on St. Croix	State mn	ZIP 55074	Property ID No./GEO Code
Owner donrovine retreat center	Pumping Date 10/07/19		
Contractor			
Maintainer Row Sewer Service	MPCA License No. L3309	Telephone Number	6514655505

What was done to the system?

Tank(s) Pumped
 Sludge and scum measured.
 Do tanks need to be pumped?
 Yes No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1000 Pumped Tank 2: Pumped
 Tank 3: Pumped Tank 4: Pumped
 Total Gallons Pumped: 1000


Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.

RECEIVED
 OCT 14 2019
PUBLIC HEALTH

*Tank Measurements-Use Only if Tank(s) Were NOT Pumped

Tank Length _____ in. Tank Width _____ in. Tank Depth _____ in. = Tank Volume (cubic inches) _____
 Tank Radius _____ in. Tank Radius _____ in. 3.14 = Tank Volume (cubic inches) _____
 Tank Volume (cu. in.) _____ / 231.01 = Liquid Capacity _____ Gallons / Tank Depth _____ in. = Gallons/Inch _____
 Sludge Level _____ in. Gallons Per Inch _____ = Sludge Volume _____ Gallons
 Scum Level _____ in. Gallons Per Inch _____ = Scum Volume _____ Gallons
 Sludge Volume _____ + Scum Volume _____ = Total Sludge and Scum Volume _____ Gallons
 Total Sludge and Scum Volume _____ / Liquid Capacity _____ = Percent Sludge and Scum in Tank _____ %



Tank Depth measured from invert of outlet pipe to bottom of tank

- *Tanks must be pumped if either of the following conditions exist:
1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Signature

Date

10/07/19

Reset Form