

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	10-17-19 Reason f	or Maintenance:	Routi	ne	
Property Address: 19	1920 Square Lak	eTAIN MA	Property Owner's N	lame: <u>al Vo</u>	shell
	zerter ZIP: 5508	/			
•	0:07144617604 M				2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☐ Sludge and scum measured ☐ Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance Hole Sother (enter authorization code)					
<ol> <li>Were all covers securely replaced? Yes □ No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? □ Yes □ No</li> </ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes 🕅 No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_ = 7
Tank #1 1,250	of septage were removed?  gal Tank #2  List any troubleshooting,  disposal:	gal Pretreatmen	t tank g nducted, tank safe	al Pump Tankety concerns, or oth	gal er concerns.

Smilie's Sewer Service **PO BOX 100** 

Scandia, MN 55073

License# 2428 P: 651-433-3934